2.003 CLEANING MAMS SCREENS

(podfall000712)

Page 1 of 2 pages

OBJECTIVE:

Microgravity Acceleration Measurement System (MAMS). Temporary removal of MAMS to clean the screens.

TOOLS:

High Torque Locker Tool

Ratchet, 1/4" Drive

1/4" Socket, 1/4" Drive

(10-50 in-lbs) Trg Wrench, 1/4" Drive

Vacuum Cleaner SEG39125637-303 (if necessary)

MATERIALS:

Gray Tape, 2" width

NOTE

- 1. The power and comm was removed by the POIC.
- 2. The screens can be cleaned with either tape or the vacuum (if debris is heavy).
- LAB102_F1 1. sw LOCKER-3 POWER → OFF √LOCKER-3 POWER Lt – Off

LAB1O2_G 1 (MAMS)

2. $cb CB \rightarrow OFF$

- 3. EXPRESS Rack Power Cable (24") ←|→POWER J1 SSPCM 5A Replace connector cover.
- 4. EXPRESS Rack Data Cable (38") ←|→DATA J3 Replace connector cover.
- 5. Secure cables as required.
- 6. Remove MAMS locker fasteners (eight) [High Torque Locker Tool; 1/4 " Socket, 1/4" drive; Ratchet, 1/4" Drive].
- 7. Position MAMS with screens facing forward and secure as required.
- 8. Remove lint from screens (three, one on lower left corner, two on right side) [Gray Tape, 2" width or Vacuum Cleaner].
- 9. Push MAMS fasteners out to engage Locker Fittings in EXPRESS Rack [High Torque Locker Tool]. See Figure 1.




Figure 1. EXPRESS Rack Locker Fitting

- 10. Thread Fasteners (eight) loosely until all fasteners engaged. Torque fasteners to 30 in-lbs [High Torque Locker Tool; 1/4 " Socket, 1/4" drive; (10-50 in-lbs) Trg Wrench, 1/4" Drive].
- 11. Remove connector cover (Captive to panel). EXPRESS Rack Power Cable (24") → |←POWER J1
- 12. Remove connector cover (Captive to panel) EXPRESS Rack Data Cable (38") →|←DATA J3
- 13. cb CB → ON
- LAB102 F1 14. sw LOCKER-3 POWER → ON
 - 15. Stow:
 Gray Tape, 2" width
 High Torque Locker Tool
 Ratchet, 1/4" Drive
 1/4" Socket, 1/4" Drive
 (10-50 in-lbs) Trq Wrench, 1/4" Drive
 Vacuum Cleaner (if required)
 - 16. Notify **POIC** of the amount of debris removed from the screens (light, medium or heavy).